2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Wright School

GovernanceDISTRICTReport TypeElementaryAddress2700 W. Dauphin St.Enrollment364Philadelphia, Pa 19132Grade Range'00-05'Phone/Fax215-684-5076 / 215-684-7018Admissions CategoryNeighborhood

Website Www.Philasd.Org/Schools/Wright Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacem	nent Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems	•	
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	38.27%	\$16,230,499	\$42,411,864
Building	40.90 %	\$16,197,263	\$39,597,760
Grounds	01.18 %	\$33,235	\$2,814,104

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,134,600
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,026,620
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,476,820
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$118,900
Interior Doors (Classroom doors)	82.87 %	\$238,529	\$287,820
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,083,220
Plumbing Fixtures	00.00 %	\$0	\$1,108,640
Boilers	42.84 %	\$655,797	\$1,530,940
Chillers/Cooling Towers	65.60 %	\$1,316,857	\$2,007,360
Radiators/Unit Ventilators/HVAC	137.27 %	\$4,839,149	\$3,525,180
Heating/Cooling Controls	158.90 %	\$1,759,069	\$1,107,000
Electrical Service and Distribution	183.00 %	\$1,455,565	\$795,400
Lighting	45.60 %	\$1,296,637	\$2,843,760
Communications and Security (Cameras, Pa System and Fire Alarm)	46.77 %	\$498,205	\$1,065,180

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.