2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Kensington Health Sciences School

Governance DISTRICT Report Type High Address 2463 Emerald St. Enrollment 459
Philadelphia, Pa 19125 Grade Range '09-12'

Phone/Fax 215-291-5185 / 215-291-6320 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Kensingtonhealthsciences Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	nent Value					
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	06.06%	\$1,837,562	\$30,333,846
Building	06.01 %	\$1,799,306	\$29,919,077
Grounds	09.45 %	\$39,196	\$414,769

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	05.62 %	\$60,854	\$1,083,320
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,436,221
Windows (Shows functionality of exterior windows)	08.90 %	\$138,156	\$1,551,963
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$65,417
Interior Doors (Classroom doors)	00.00 %	\$0	\$212,041
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$893,281
Plumbing Fixtures	00.00 %	\$0	\$762,447
Boilers	00.00 %	\$0	\$1,052,876
Chillers/Cooling Towers	00.00 %	\$0	\$1,380,525
Radiators/Unit Ventilators/HVAC	00.29 %	\$6,983	\$2,424,378
Heating/Cooling Controls	126.09 %	\$959,948	\$761,319
Electrical Service and Distribution	00.00 %	\$0	\$547,022
Lighting	03.76 %	\$73,597	\$1,955,744
Communications and Security (Cameras, Pa System and Fire Alarm)	46.53 %	\$340,855	\$732,558

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.