#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Ziegler School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 5935 Saul St.
 Enrollment
 539

 Philadelphia, Pa 19149
 Grade Range
 '00-08'

Phone/Fax 215-537-2510 / 215-537-2987 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Ziegler Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies						
Replacement Value						
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	19.58%	\$6,127,753	\$31,290,331
Building	19.72 %	\$6,065,285	\$30,750,681
Grounds	08.77 %	\$49,047	\$559,371

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	33.95 %	\$379,086	\$1,116,577
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.93 %	\$42,106	\$2,178,613
Windows (Shows functionality of exterior windows)	89.28 %	\$949,047	\$1,063,040
Exterior Doors (Shows condition of exterior doors)	18.75 %	\$16,044	\$85,586
Interior Doors (Classroom doors)	09.21 %	\$19,082	\$207,178
Interior Walls (Paint and Finishes)	02.19 %	\$17,134	\$782,350
Plumbing Fixtures	34.75 %	\$277,302	\$798,018
Boilers	00.00 %	\$0	\$1,101,997
Chillers/Cooling Towers	38.90 %	\$562,093	\$1,444,932
Radiators/Unit Ventilators/HVAC	83.09 %	\$2,108,463	\$2,537,485
Heating/Cooling Controls	67.30 %	\$536,300	\$796,838
Electrical Service and Distribution	00.00 %	\$0	\$1,717,629
Lighting	00.24 %	\$4,943	\$2,046,987
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$766,735

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.