#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### Allen, Ethel School

Governance DISTRICT Report Type Elementarymiddle

Address 3200 W. Lehigh Ave. Enrollment 519
Philadelphia, Pa 19132 Grade Range '00-08'

Phone/Fax 215-227-4404 / 215-227-2971 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Ethelallen Turnaround Model Turnaround

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies		
raciiit	y Condition index (FCI)	Replacem	Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%	
		Buildings			
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.	
		Systems	•		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program	

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	09.04%	\$4,002,157	\$44,284,672
Building	09.10 %	\$3,757,425	\$41,291,437
Grounds	08.18 %	\$244,732	\$2,993,235

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,590,912
Exterior Walls (Shows condition of the structural condition of the exterior facade)	03.15 %	\$96,868	\$3,070,801
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,498,378
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$120,636
Interior Doors (Classroom doors)	32.67 %	\$95,412	\$292,021
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,099,032
Plumbing Fixtures	00.00 %	\$0	\$1,124,823
Boilers	00.00 %	\$0	\$1,553,288
Chillers/Cooling Towers	00.00 %	\$0	\$2,036,663
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$3,576,639
Heating/Cooling Controls	00.00 %	\$0	\$1,123,160
Electrical Service and Distribution	132.04 %	\$1,065,563	\$807,011
Lighting	08.55 %	\$246,563	\$2,885,272
Communications and Security (Cameras, Pa System and Fire Alarm)	05.76 %	\$62,274	\$1,080,729

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.