2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Rowen School

GovernanceDISTRICTReport TypeElementaryAddress6841 N. 19Th St.Enrollment497Philadelphia, Pa 19126Grade Range'00-05'Phone/Fax215-276-5251 / 215-276-5806Admissions CategoryNeighborhood

Website Www.Philasd.Org/Schools/Rowen Turnaround Model N/A

Building/System FCI Tiers

| Eacilit | v Candition Inday (ECI) | | ed Deficiencies | | | |
|--|-------------------------------|---|---|--|--|--|
| Facility Condition Index (FCI) = Replacement Value | | | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | |
| Buildings | | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | |
| Systems | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 36.86% | \$12,950,326 | \$35,134,684 |
| Building | 37.30 % | \$12,803,357 | \$34,321,171 |
| Grounds | 08.48 % | \$146,969 | \$1,733,961 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 86.30 % | \$866,905 | \$1,004,479 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.00 % | \$0 | \$1,760,808 |
| Windows (Shows functionality of exterior windows) | 00.00 % | \$0 | \$768,732 |
| Exterior Doors (Shows condition of exterior doors) | 00.00 % | \$0 | \$94,188 |
| Interior Doors (Classroom doors) | 17.06 % | \$36,177 | \$212,064 |
| Interior Walls (Paint and Finishes) | 00.00 % | \$0 | \$1,109,952 |
| Plumbing Fixtures | 26.21 % | \$466,848 | \$1,781,112 |
| Boilers | 115.62 % | \$1,217,415 | \$1,052,988 |
| Chillers/Cooling Towers | 67.49 % | \$931,773 | \$1,380,672 |
| Radiators/Unit Ventilators/HVAC | 133.83 % | \$3,244,980 | \$2,424,636 |
| Heating/Cooling Controls | 158.90 % | \$1,209,898 | \$761,400 |
| Electrical Service and Distribution | 117.92 % | \$645,135 | \$547,080 |
| Lighting | 32.57 % | \$637,017 | \$1,955,952 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 48.57 % | \$355,830 | \$732,636 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.