### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Edison School**

Governance DISTRICT Report Type High
Address 151 W. Luzerne St. Enrollment 1056
Philadelphia, Pa 19140 Grade Range '09-12'
Phone/Fax 215-234-9599 / 215-239-5824 Admissions Category Neighbort

Phone/Fax 215-324-9599 / 215-329-5824 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Edison Turnaround Model Turnaround

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	26.71%	\$47,842,768	\$179,104,911
Building	24.68 %	\$41,422,525	\$167,840,096
Grounds	58.49 %	\$6,420,243	\$10,977,255

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.05 %	\$3,355	\$6,131,488
Exterior Walls (Shows condition of the structural condition of the exterior facade)	02.47 %	\$336,720	\$13,651,200
Windows (Shows functionality of exterior windows)	94.20 %	\$8,191,705	\$8,696,320
Exterior Doors (Shows condition of exterior doors)	124.23 %	\$455,366	\$366,560
Interior Doors (Classroom doors)	00.00 %	\$0	\$1,188,160
Interior Walls (Paint and Finishes)	78.49 %	\$3,928,849	\$5,005,440
Plumbing Fixtures	01.42 %	\$60,634	\$4,272,320
Boilers	10.75 %	\$634,176	\$5,899,720
Chillers/Cooling Towers	58.57 %	\$4,530,940	\$7,735,680
Radiators/Unit Ventilators/HVAC	72.84 %	\$9,894,627	\$13,584,840
Heating/Cooling Controls	136.47 %	\$5,821,809	\$4,266,000
Electrical Service and Distribution	00.00 %	\$0	\$3,065,200
Lighting	00.00 %	\$0	\$10,958,880
Communications and Security (Cameras, Pa System and Fire Alarm)	17.23 %	\$707,398	\$4,104,840

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.