2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Stanton, E M School

Phone/Fax

Governance DISTRICT Report Type Elementarymiddle

Address 1700 Christian St. Enrollment 267
Philadelphia Pa 19146 Grade Range '00-08'

 Philadelphia, Pa 19146
 Grade Range
 '00-08'

 215-875-3185 / 215-875-3711
 Admissions Category
 Neighborhood

Website Www.Philasd.Org/Schools/Emstanton Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	36.64%	\$7,598,751	\$20,737,083
Building	36.42 %	\$7,514,715	\$20,633,634
Grounds	19.60 %	\$84,036	\$428,649

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.46 %	\$2,035	\$440,454
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.52 %	\$22,460	\$1,476,400
Windows (Shows functionality of exterior windows)	122.58 %	\$883,075	\$720,400
Exterior Doors (Shows condition of exterior doors)	12.05 %	\$6,987	\$58,000
Interior Doors (Classroom doors)	17.44 %	\$24,489	\$140,400
Interior Walls (Paint and Finishes)	09.19 %	\$58,256	\$633,600
Plumbing Fixtures	36.28 %	\$196,199	\$540,800
Boilers	43.91 %	\$655,797	\$1,493,600
Chillers/Cooling Towers	49.20 %	\$481,782	\$979,200
Radiators/Unit Ventilators/HVAC	38.88 %	\$668,626	\$1,719,600
Heating/Cooling Controls	119.18 %	\$643,563	\$540,000
Electrical Service and Distribution	177.43 %	\$688,438	\$388,000
Lighting	37.96 %	\$526,622	\$1,387,200
Communications and Security (Cameras, Pa System and Fire Alarm)	53.84 %	\$279,772	\$519,600

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.