#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## Washington, Grover Middle School

Governance DISTRICT Report Type Middle
Address 201 E. Olney Ave. Enrollment 553
Philadelphia, Pa 19120 Grade Range '05-08'

Phone/Fax 215-456-0422 / 215-456-2181 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Grover Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacen	Replacement Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	04.56%	\$3,705,407	\$81,305,518
Building	04.37 %	\$3,471,556	\$79,459,199
Grounds	12.58 %	\$233,853	\$1,858,880

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$4,327,059
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.17 %	\$11,004	\$6,545,110
Windows (Shows functionality of exterior windows)	01.20 %	\$38,377	\$3,199,300
Exterior Doors (Shows condition of exterior doors)	05.51 %	\$11,945	\$216,775
Interior Doors (Classroom doors)	12.26 %	\$64,353	\$524,745
Interior Walls (Paint and Finishes)	01.07 %	\$26,936	\$2,513,095
Plumbing Fixtures	00.37 %	\$7,579	\$2,021,240
Boilers	00.00 %	\$0	\$2,791,165
Chillers/Cooling Towers	07.76 %	\$284,006	\$3,659,760
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$6,427,005
Heating/Cooling Controls	133.12 %	\$2,686,710	\$2,018,250
Electrical Service and Distribution	00.00 %	\$0	\$1,450,150
Lighting	00.00 %	\$0	\$5,184,660
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$1,942,005

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.