2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Hamilton School

Governance DISTRICT Report Type Elementarymiddle

Address 5640 Spruce St. Enrollment 579
Philadelphia, Pa 19139 Grade Range '00-08'

Phone/Fax 215-471-2911 / 215-471-2724 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hamilton Turnaround Model N/A

Building/System FCI Tiers

Facilit	v Candition Inday (FCI)	Cost of Assessed Deficiencies					
Facility Condition Index (FCI) =		Replacement Value					
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	64.79%	\$30,084,893	\$46,436,758
Building	63.08 %	\$28,328,697	\$44,906,143
Grounds	113.61 %	\$1,756,196	\$1,545,830

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	90.59 %	\$1,161,655	\$1,282,260
Exterior Walls (Shows condition of the structural condition of the exterior facade)	28.85 %	\$952,921	\$3,303,445
Windows (Shows functionality of exterior windows)	43.17 %	\$695,928	\$1,611,895
Exterior Doors (Shows condition of exterior doors)	49.91 %	\$64,769	\$129,775
Interior Doors (Classroom doors)	177.79 %	\$558,521	\$314,145
Interior Walls (Paint and Finishes)	68.88 %	\$1,212,524	\$1,760,465
Plumbing Fixtures	23.70 %	\$286,797	\$1,210,040
Boilers	74.64 %	\$1,247,246	\$1,670,965
Chillers/Cooling Towers	00.00 %	\$0	\$2,190,960
Radiators/Unit Ventilators/HVAC	239.78 %	\$9,225,626	\$3,847,605
Heating/Cooling Controls	158.90 %	\$1,919,960	\$1,208,250
Electrical Service and Distribution	138.74 %	\$1,204,500	\$868,150
Lighting	27.19 %	\$843,797	\$3,103,860
Communications and Security (Cameras, Pa System and Fire Alarm)	15.94 %	\$185,295	\$1,162,605

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.