#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Saul Annex 5 School**

Governance DISTRICT Report Type High

Address 7100 Henry Ave. Enrollment

Philadelphia, Pa 19128 Grade Range '09-12'
Phone/Fax 215-487-4467 / 215-487-4844 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Saul Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacen	nent Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	34.52%	\$4,451,674	\$12,895,181
Building	46.54 %	\$3,979,084	\$8,550,285
Grounds	10.80 %	\$472,590	\$4,375,133

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.14 %	\$528,051	\$599,125
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$486,595
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$212,437
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$26,029
Interior Doors (Classroom doors)	81.41 %	\$47,706	\$58,603
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$205,891
Plumbing Fixtures	00.00 %	\$0	\$492,206
Boilers	#DIV/0! %	\$0	\$0
Chillers/Cooling Towers	00.00 %	\$0	\$0
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$0
Heating/Cooling Controls	158.90 %	\$334,351	\$210,411
Electrical Service and Distribution	21.47 %	\$32,461	\$151,184
Lighting	44.74 %	\$241,829	\$540,522
Communications and Security (Cameras, Pa System and Fire Alarm)	67.98 %	\$137,629	\$202,462

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.