2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Rhawnhurst School

Governance DISTRICT Report Type Elementary Address 7809 Castor Ave. Enrollment 598 '00-05' Philadelphia, Pa 19152 Grade Range 215-728-5013 / 215-728-5931

Phone/Fax **Admissions Category** Neighborhood

Website Www.Philasd.Org/Schools/Rhawnhurst Turnaround Model N/A

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	45.98%	\$14,241,292	\$30,976,025
Building	52.18 %	\$13,962,987	\$26,761,288
Grounds	05.96 %	\$278,306	\$4,667,901

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	86.31 %	\$1,331,783	\$1,543,104
Exterior Walls (Shows condition of the structural condition of the exterior facade)	08.97 %	\$128,834	\$1,436,120
Windows (Shows functionality of exterior windows)	159.68 %	\$1,001,146	\$626,980
Exterior Doors (Shows condition of exterior doors)	136.43 %	\$104,809	\$76,820
Interior Doors (Classroom doors)	308.14 %	\$532,958	\$172,960
Interior Walls (Paint and Finishes)	03.36 %	\$20,415	\$607,660
Plumbing Fixtures	31.96 %	\$464,332	\$1,452,680
Boilers	120.97 %	\$1,038,883	\$858,820
Chillers/Cooling Towers	65.60 %	\$738,718	\$1,126,080
Radiators/Unit Ventilators/HVAC	208.52 %	\$4,123,645	\$1,977,540
Heating/Cooling Controls	158.90 %	\$986,794	\$621,000
Electrical Service and Distribution	157.91 %	\$704,615	\$446,200
Lighting	08.04 %	\$128,311	\$1,595,280
Communications and Security (Cameras, Pa System and Fire Alarm)	83.35 %	\$498,043	\$597,540

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.