2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Mitchell School

Governance DISTRICT Report Type Elementarymiddle

Address 5500 Kingsessing Ave. Enrollment 547
Philadelphia, Pa 19143 Grade Range '00-08'

Phone/Fax 215-727-2160 / 215-727-2218 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Mitchell Turnaround Model Turnaround

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies			
raciiit	y condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
	•	Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	34.12%	\$15,934,147	\$46,707,127
Building	34.77 %	\$15,770,876	\$45,352,938
Grounds	10.58 %	\$163,271	\$1,543,549

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,331,418
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,321,900
Windows (Shows functionality of exterior windows)	34.24 %	\$555,076	\$1,620,900
Exterior Doors (Shows condition of exterior doors)	212.04 %	\$276,713	\$130,500
Interior Doors (Classroom doors)	131.96 %	\$416,873	\$315,900
Interior Walls (Paint and Finishes)	74.84 %	\$1,130,962	\$1,511,100
Plumbing Fixtures	01.85 %	\$22,503	\$1,216,800
Boilers	00.00 %	\$0	\$1,680,300
Chillers/Cooling Towers	49.20 %	\$1,084,009	\$2,203,200
Radiators/Unit Ventilators/HVAC	115.21 %	\$4,457,749	\$3,869,100
Heating/Cooling Controls	132.68 %	\$1,612,026	\$1,215,000
Electrical Service and Distribution	89.17 %	\$778,468	\$873,000
Lighting	06.03 %	\$188,094	\$3,121,200
Communications and Security (Cameras, Pa System and Fire Alarm)	32.90 %	\$384,576	\$1,169,100

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.