#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Wister School**

GovernanceCHARTERReport TypeElementaryAddress67 E. Bringhurst St.Enrollment522Philadelphia, Pa 19144Grade Range'00-05'

Phone/Fax N/A / N/A Admissions Category Neighborhood
Website Http://www.Masterycharter.Org/Schools/Elementary- Turnaround Model Renaissance Charter

Schools/John-Wister-Elementary/

## **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	45.35%	\$22,482,848	\$49,573,984
Building	46.24 %	\$22,014,447	\$47,612,533
Grounds	21.02 %	\$468,401	\$2,228,539

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.33 %	\$1,118,716	\$1,252,383
Exterior Walls (Shows condition of the structural condition of the exterior facade)	09.60 %	\$332,176	\$3,459,021
Windows (Shows functionality of exterior windows)	118.50 %	\$1,999,981	\$1,687,807
Exterior Doors (Shows condition of exterior doors)	215.30 %	\$292,567	\$135,887
Interior Doors (Classroom doors)	105.53 %	\$347,127	\$328,940
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,844,312
Plumbing Fixtures	37.21 %	\$471,516	\$1,267,027
Boilers	14.03 %	\$245,555	\$1,749,659
Chillers/Cooling Towers	48.30 %	\$1,108,098	\$2,294,143
Radiators/Unit Ventilators/HVAC	107.68 %	\$4,338,156	\$4,028,808
Heating/Cooling Controls	157.69 %	\$1,995,045	\$1,265,153
Electrical Service and Distribution	87.35 %	\$794,010	\$909,036
Lighting	28.86 %	\$937,894	\$3,250,036
Communications and Security (Cameras, Pa System and Fire Alarm)	61.73 %	\$751,502	\$1,217,358

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.