### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### **Lamberton LSH School**

Governance DISTRICT Report Type Elementarymiddle

Address 7501 Woodbine Ave. Enrollment

Philadelphia, Pa 19151 Grade Range '00-08'

Phone/Fax215-581-5650 / 215-581-3403Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/LambertonTurnaround ModelN/A

# **Building/System FCI Tiers**

Eacility	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiic	y condition maex (FCI)	Replacem	nent Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	03.77%	\$622,331	\$16,500,972
Building	00.44 %	\$68,062	\$15,356,912
Grounds	18.86 %	\$554,269	\$2,939,551

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	01.28 %	\$17,630	\$1,381,174
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$785,433
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$342,904
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$42,014
Interior Doors (Classroom doors)	00.00 %	\$0	\$94,594
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$422,906
Plumbing Fixtures	00.00 %	\$0	\$794,490
Boilers	00.00 %	\$0	\$469,700
Chillers/Cooling Towers	00.00 %	\$0	\$615,868
Radiators/Unit Ventilators/HVAC	00.94 %	\$10,173	\$1,081,542
Heating/Cooling Controls	00.00 %	\$0	\$339,633
Electrical Service and Distribution	00.00 %	\$0	\$244,033
Lighting	00.00 %	\$0	\$872,479
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$326,802

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.