2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Brown, H A School

Governance DISTRICT Report Type Elementarymiddle

Address 1946 E. Sergeant St. Enrollment '00-08'

Philadelphia, Pa 19125 **Grade Range**

215-291-4717 / 215-291-5836 Admissions Category Neighborhood Phone/Fax

Website Www.Philasd.Org/Schools/Habrown Turnaround Model N/A

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	18.79%	\$6,379,873	\$33,947,654
Building	18.68 %	\$6,304,130	\$33,742,286
Grounds	36.64 %	\$75,744	\$206,724

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	55.62 %	\$630,205	\$1,133,092
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.33 %	\$8,322	\$2,502,313
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,220,988
Exterior Doors (Shows condition of exterior doors)	120.44 %	\$118,395	\$98,303
Interior Doors (Classroom doors)	00.00 %	\$0	\$237,960
Interior Walls (Paint and Finishes)	03.03 %	\$34,547	\$1,139,634
Plumbing Fixtures	22.63 %	\$207,446	\$916,588
Boilers	40.47 %	\$512,233	\$1,265,733
Chillers/Cooling Towers	00.00 %	\$0	\$1,659,622
Radiators/Unit Ventilators/HVAC	72.26 %	\$2,106,135	\$2,914,507
Heating/Cooling Controls	158.92 %	\$1,454,452	\$915,233
Electrical Service and Distribution	00.00 %	\$0	\$657,612
Lighting	00.00 %	\$0	\$2,351,131
Communications and Security (Cameras, Pa System and Fire Alarm)	05.32 %	\$46,861	\$880,657

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.