2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Munoz-Marin School

Governance DISTRICT Report Type Elementarymiddle

Address 3300 N. 3Rd St. Enrollment 647
Philadelphia, Pa 19140 Grade Range '00-08'
Phone/Fax 215-291-8825 / 215-291-8845 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Marin Turnaround Model Turnaround

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	19.73%	\$12,105,450	\$61,367,415
Building	19.82 %	\$11,869,775	\$59,874,292
Grounds	15.78 %	\$235,675	\$1,493,123

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.44 %	\$1,951,604	\$2,182,131
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$4,401,518
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$2,147,693
Exterior Doors (Shows condition of exterior doors)	136.71 %	\$236,397	\$172,913
Interior Doors (Classroom doors)	00.00 %	\$0	\$418,568
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$2,004,594
Plumbing Fixtures	04.70 %	\$75,792	\$1,612,260
Boilers	10.64 %	\$236,958	\$2,226,398
Chillers/Cooling Towers	21.22 %	\$619,332	\$2,919,240
Radiators/Unit Ventilators/HVAC	35.69 %	\$1,829,914	\$5,126,558
Heating/Cooling Controls	132.68 %	\$2,135,935	\$1,609,875
Electrical Service and Distribution	00.00 %	\$0	\$1,156,725
Lighting	26.76 %	\$1,106,729	\$4,135,590
Communications and Security (Cameras, Pa System and Fire Alarm)	39.54 %	\$612,456	\$1,549,058

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.