### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Houston School**

Governance DISTRICT Report Type Elementarymiddle

 Address
 7300 Rural Ln.
 Enrollment
 391

 Philadelphia, Pa 19119
 Grade Range
 '00-08'

Phone/Fax 215-248-6608 / 215-248-6683 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Houston Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	39.94%	\$15,129,002	\$37,882,431
Building	40.31 %	\$14,624,204	\$36,276,843
Grounds	22.09 %	\$387,662	\$1,754,628

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$1,070,306
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.56 %	\$41,574	\$2,657,520
Windows (Shows functionality of exterior windows)	00.82 %	\$10,592	\$1,296,720
Exterior Doors (Shows condition of exterior doors)	35.39 %	\$36,951	\$104,400
Interior Doors (Classroom doors)	16.52 %	\$41,743	\$252,720
Interior Walls (Paint and Finishes)	04.45 %	\$50,804	\$1,140,480
Plumbing Fixtures	00.00 %	\$0	\$973,440
Boilers	00.00 %	\$0	\$1,344,240
Chillers/Cooling Towers	63.72 %	\$1,123,153	\$1,762,560
Radiators/Unit Ventilators/HVAC	177.47 %	\$5,493,077	\$3,095,280
Heating/Cooling Controls	158.90 %	\$1,544,551	\$972,000
Electrical Service and Distribution	99.96 %	\$698,095	\$698,400
Lighting	34.29 %	\$856,239	\$2,496,960
Communications and Security (Cameras, Pa System and Fire Alarm)	73.42 %	\$686,656	\$935,280

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.