### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Solis-Cohen PEC School**

Governance DISTRICT Report Type Elementary

Address 7001 Horrocks St. Enrollment

Philadelphia, Pa 19149 Grade Range '00-05'

 Phone/Fax
 215-728-5012 / 215-728-5982
 Admissions Category
 Neighborhood

 Website
 Www.Philasd.Org/Schools/Solis Turnaround Model
 N/A

Www.Philasd.Org/Schools/Solis- Turnaround Model N/A Cohen

## **Building/System FCI Tiers**

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	04.70%	\$978,076	\$20,799,850
Building	00.06 %	\$8,310	\$14,855,094
Grounds	16.31 %	\$969,766	\$5,944,756

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,335,443
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.04 %	\$337	\$759,427
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$331,550
Exterior Doors (Shows condition of exterior doors)	10.59 %	\$4,302	\$40,623
Interior Doors (Classroom doors)	04.01 %	\$3,671	\$91,462
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$408,903
Plumbing Fixtures	00.00 %	\$0	\$768,184
Boilers	00.00 %	\$0	\$454,148
Chillers/Cooling Towers	00.00 %	\$0	\$595,476
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$1,045,732
Heating/Cooling Controls	00.00 %	\$0	\$328,388
Electrical Service and Distribution	00.00 %	\$0	\$235,953
Lighting	00.00 %	\$0	\$843,591
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$315,982

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.