2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Carnell School

Website

Governance DISTRICT Report Type Elementary Address 1100 Devereaux Ave. Enrollment 979 '00-05' Philadelphia, Pa 19111 **Grade Range**

215-537-2527 / 215-537-6305 Admissions Category Phone/Fax Neighborhood Www.Philasd.Org/Schools/Carnell Turnaround Model

School Redesign Initiative

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	56.26%	\$22,454,832	\$39,911,930
Building	58.78 %	\$22,067,850	\$37,545,427
Grounds	15.37 %	\$386,982	\$2,518,520

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.88 %	\$877,544	\$987,327
Exterior Walls (Shows condition of the structural condition of the exterior facade)	02.19 %	\$60,622	\$2,764,005
Windows (Shows functionality of exterior windows)	132.83 %	\$1,791,476	\$1,348,679
Exterior Doors (Shows condition of exterior doors)	38.61 %	\$41,924	\$108,583
Interior Doors (Classroom doors)	436.66 %	\$1,147,753	\$262,846
Interior Walls (Paint and Finishes)	24.02 %	\$302,350	\$1,258,817
Plumbing Fixtures	52.14 %	\$527,933	\$1,012,445
Boilers	93.83 %	\$1,311,841	\$1,398,103
Chillers/Cooling Towers	65.70 %	\$1,204,455	\$1,833,185
Radiators/Unit Ventilators/HVAC	192.08 %	\$6,183,555	\$3,219,306
Heating/Cooling Controls	170.09 %	\$1,719,495	\$1,010,948
Electrical Service and Distribution	122.29 %	\$888,300	\$726,385
Lighting	67.52 %	\$1,753,548	\$2,597,012
Communications and Security (Cameras, Pa System and Fire Alarm)	20.94 %	\$203,735	\$972,756

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.