#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **MLK High School**

Governance DISTRICT Report Type High
Address 6100 Stenton Ave. Enrollment 790
Philadelphia, Pa 19138 Grade Range '09-12'
Phone/Fax 215-276-5253 / 215-276-5844 Admissions Category Neighborh

Phone/Fax 215-276-5253 / 215-276-5844 Admissions Category Neighborhood Website Www.Philasd.Org/Schools/Mlking Turnaround Model Turnaround

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacen	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	39.81%	\$82,498,630	\$207,234,719
Building	42.86 %	\$79,132,710	\$184,609,230
Grounds	14.88 %	\$3,365,920	\$22,625,489

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$4,167,487	\$4,651,860
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.61 %	\$96,868	\$15,984,000
Windows (Shows functionality of exterior windows)	14.25 %	\$1,451,171	\$10,182,400
Exterior Doors (Shows condition of exterior doors)	148.54 %	\$637,512	\$429,200
Interior Doors (Classroom doors)	102.87 %	\$1,431,176	\$1,391,200
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$4,676,100
Plumbing Fixtures	00.00 %	\$0	\$5,002,400
Boilers	25.40 %	\$1,754,290	\$6,907,900
Chillers/Cooling Towers	69.19 %	\$6,266,622	\$9,057,600
Radiators/Unit Ventilators/HVAC	197.89 %	\$31,477,448	\$15,906,300
Heating/Cooling Controls	136.47 %	\$6,816,675	\$4,995,000
Electrical Service and Distribution	128.45 %	\$4,610,111	\$3,589,000
Lighting	11.57 %	\$1,484,053	\$12,831,600
Communications and Security (Cameras, Pa System and Fire Alarm)	02.56 %	\$123,152	\$4,806,300

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.