2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Richmond School

Governance DISTRICT Report Type Elementary
Address 2944 Belgrade St. Enrollment 672
Philadelphia, Pa 19134 Grade Range '00-05'

Phone/Fax 215-291-4718 / 215-291-4141 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Richmond Turnaround Model N/A

Building/System FCI Tiers

Eacilit	v Candition Inday (ECI)	_ Cost of Assess	ed Deficiencies				
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	81.15%	\$17,440,503	\$21,490,483
Building	79.03 %	\$16,748,313	\$21,193,242
Grounds	91.20 %	\$692,190	\$758,946

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	107.61 %	\$593,525	\$551,541
Exterior Walls (Shows condition of the structural condition of the exterior facade)	63.24 %	\$982,995	\$1,554,294
Windows (Shows functionality of exterior windows)	232.77 %	\$1,766,211	\$758,793
Exterior Doors (Shows condition of exterior doors)	391.53 %	\$238,277	\$60,858
Interior Doors (Classroom doors)	65.62 %	\$95,082	\$144,900
Interior Walls (Paint and Finishes)	148.16 %	\$807,917	\$545,307
Plumbing Fixtures	46.19 %	\$267,026	\$578,151
Boilers	91.38 %	\$730,041	\$798,882
Chillers/Cooling Towers	65.21 %	\$683,196	\$1,047,627
Radiators/Unit Ventilators/HVAC	169.20 %	\$3,111,139	\$1,838,781
Heating/Cooling Controls	155.54 %	\$897,743	\$577,185
Electrical Service and Distribution	170.63 %	\$642,842	\$376,740
Lighting	51.12 %	\$689,305	\$1,348,536
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$505,218

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.