2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Hartranft School

Governance DISTRICT Report Type Elementarymiddle

Address 720 W. Cumberland St. Enrollment 526
Philadelphia, Pa 19133 Grade Range '00-08'

Phone/Fax 215-684-5088 / 215-765-6515 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hartranft Turnaround Model N/A

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	47.17%	\$20,478,689	\$43,417,452
Building	44.51 %	\$18,869,645	\$42,392,474
Grounds	165.29 %	\$1,473,647	\$891,528

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.46 %	\$1,534,855	\$1,715,628
Exterior Walls (Shows condition of the structural condition of the exterior facade)	23.19 %	\$727,421	\$3,137,350
Windows (Shows functionality of exterior windows)	93.05 %	\$1,424,514	\$1,530,850
Exterior Doors (Shows condition of exterior doors)	221.68 %	\$273,220	\$123,250
Interior Doors (Classroom doors)	191.88 %	\$572,470	\$298,350
Interior Walls (Paint and Finishes)	80.17 %	\$900,240	\$1,122,850
Plumbing Fixtures	18.49 %	\$212,460	\$1,149,200
Boilers	00.00 %	\$0	\$1,586,950
Chillers/Cooling Towers	00.00 %	\$0	\$2,080,800
Radiators/Unit Ventilators/HVAC	87.10 %	\$3,182,753	\$3,654,150
Heating/Cooling Controls	158.90 %	\$1,823,425	\$1,147,500
Electrical Service and Distribution	110.31 %	\$909,465	\$824,500
Lighting	36.58 %	\$1,078,193	\$2,947,800
Communications and Security (Cameras, Pa System and Fire Alarm)	44.72 %	\$493,781	\$1,104,150

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.