#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## **Franklin Learning Center School**

 Governance
 DISTRICT
 Report Type
 High

 Address
 616 N. 15Th St.
 Enrollment
 868

 Philadelphia, Pa 19130
 Grade Range
 '09-12'

Phone/Fax 215-684-5916 / 215-684-8969 Admissions Category Special Admit

Website Www.Flc.Phila.K12.Pa.Us Turnaround Model N/A

# **Building/System FCI Tiers**

| Eacilit                                     | y Condition Index (FCI)       |   | ed Deficiencies   |  |
|---|-------------------------------|---|---|--|
| raciiit                                     | y Condition index (FCI)       | Replacement Value   |   |  |
| < 15%                                       | 15 to 25%                     | 25 to 45%   | 45 to 60%   | > 60%  |
|   |                               | Buildings   |   |  |
| Minimal Current Capital<br>Funding Required | Refurbish Systems in building | Replace Systems in building.                                  | Building should be considered for major renovation.                                   | Building should be considered for closing/replacement.   |
|   |                               | Systems   |   |  |
| Perform routine maintenance on system       | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program |

### **Building and Grounds**

|          | FCI      | Repair Costs | Replacement Cost |
|----------|----------|--------------|------------------|
| Overall  | 32.89%   | \$25,479,961 | \$77,461,039     |
| Building | 31.72 %  | \$24,727,454 | \$77,956,088     |
| Grounds  | 103.43 % | \$752,508    | \$727,586        |

## **Major Building Systems**

| Building System   | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof)   | 88.79 %    | \$1,240,806  | \$1,397,453      |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 02.49 %    | \$161,447    | \$6,480,000      |
| Windows (Shows functionality of exterior windows)                                   | 00.00 %    | \$0          | \$4,128,000      |
| Exterior Doors (Shows condition of exterior doors)                                  | 48.74 %    | \$84,804     | \$174,000        |
| Interior Doors (Classroom doors)  | 126.75 %   | \$714,848    | \$564,000        |
| Interior Walls (Paint and Finishes)   | 39.65 %    | \$999,699    | \$2,521,500      |
| Plumbing Fixtures   | 02.24 %    | \$45,475     | \$2,028,000      |
| Boilers   | #DIV/0! %  | \$0          | \$0              |
| Chillers/Cooling Towers   | 64.65 %    | \$2,373,882  | \$3,672,000      |
| Radiators/Unit Ventilators/HVAC   | 104.30 %   | \$6,725,944  | \$6,448,500      |
| Heating/Cooling Controls  | 132.68 %   | \$2,686,710  | \$2,025,000      |
| Electrical Service and Distribution   | 66.09 %    | \$961,673    | \$1,455,000      |
| Lighting  | 48.24 %    | \$2,509,611  | \$5,202,000      |
| Communications and Security (Cameras, Pa System and Fire Alarm)                     | 11.55 %    | \$225,120    | \$1,948,500      |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.