2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Kenderton School

Governance DISTRICT Report Type Elementarymiddle

 Address
 1500 W. Ontario St.
 Enrollment
 477

 Philadelphia, Pa 19140
 Grade Range
 '00-08'

Phone/Fax 215-400-8340 / 215-400-8341 Admissions Category Neighborhood

Website N/A Turnaround Model N/A

Building/System FCI Tiers

| Facility Condition Index (FCI) = Cost of Assessed Deficiencies | | | | | | | |
|--|-------------------------------|---|---|--|--|--|--|
| raciiit | y Condition index (FCI) | Replacem | Replacement Value | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | | |
| Buildings | | | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | | |
| Systems | | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 49.03% | \$21,343,136 | \$43,527,148 |
| Building | 49.37 % | \$20,993,488 | \$42,521,981 |
| Grounds | 34.72 % | \$349,648 | \$1,006,987 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 89.59 % | \$609,876 | \$680,760 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.00 % | \$0 | \$3,359,105 |
| Windows (Shows functionality of exterior windows) | 211.18 % | \$3,461,355 | \$1,639,054 |
| Exterior Doors (Shows condition of exterior doors) | 75.92 % | \$100,181 | \$131,962 |
| Interior Doors (Classroom doors) | 179.21 % | \$572,470 | \$319,438 |
| Interior Walls (Paint and Finishes) | 00.00 % | \$0 | \$1,202,216 |
| Plumbing Fixtures | 31.90 % | \$392,527 | \$1,230,428 |
| Boilers | 89.36 % | \$1,518,308 | \$1,699,119 |
| Chillers/Cooling Towers | 65.60 % | \$1,461,516 | \$2,227,876 |
| Radiators/Unit Ventilators/HVAC | 133.55 % | \$5,225,112 | \$3,912,434 |
| Heating/Cooling Controls | 132.68 % | \$1,630,079 | \$1,228,608 |
| Electrical Service and Distribution | 110.48 % | \$975,324 | \$882,778 |
| Lighting | 08.48 % | \$267,752 | \$3,156,157 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 29.13 % | \$344,326 | \$1,182,194 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.