2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Hopkinson LSH School

Governance DISTRICT Report Type Elementarymiddle

Address 4001 L St. Enrollment

Philadelphia, Pa 19124 Grade Range '00-08'
Phone/Fax 215-537-2526 / 215-537-2900 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hopkinson Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacen	nent Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems		
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	07.13%	\$767,242	\$10,754,458
Building	05.84 %	\$555,675	\$9,519,898
Grounds	17.14 %	\$211,567	\$1,234,560

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$637,071
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$499,770
Windows (Shows functionality of exterior windows)	02.25 %	\$4,912	\$218,189
Exterior Doors (Shows condition of exterior doors)	60.88 %	\$16,274	\$26,733
Interior Doors (Classroom doors)	28.11 %	\$16,922	\$60,190
Interior Walls (Paint and Finishes)	08.88 %	\$22,506	\$253,567
Plumbing Fixtures	00.00 %	\$0	\$505,533
Boilers	00.00 %	\$0	\$298,869
Chillers/Cooling Towers	00.00 %	\$0	\$391,876
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$688,184
Heating/Cooling Controls	158.82 %	\$343,231	\$216,108
Electrical Service and Distribution	00.00 %	\$0	\$155,278
Lighting	00.32 %	\$1,765	\$555,157
Communications and Security (Cameras, Pa System and Fire Alarm)	70.43 %	\$146,460	\$207,944

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.