2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Feltonville Arts and Sciences School

Governance DISTRICT Report Type Middle Address 210 E. Courtland St. Enrollment 553 Philadelphia, Pa 19120 Grade Range '06-08'

Phone/Fax 215-456-5603 / 215-456-5614 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Feltonville- Turnaround Model N/A

Arts-And-Sciences

Building/System FCI Tiers

| Cost of Assessed Deficiencies | | | | | | | |
|--|-------------------------------|---|--|--|--|--|--|
| Facility Condition Index (FCI) = Replacement Value | | | | | | | |
| < 15% | 15 to 25% | 25 to 45% | 45 to 60% | > 60% | | | |
| Buildings | | | | | | | |
| Minimal Current Capital Funding Required | Refurbish Systems in building | Replace Systems in building. | Building should be considered for major renovation. | Building should be considered for closing/replacement. | | | |
| Systems | | | | | | | |
| Perform routine maintenance on system | System requires minor repairs | System should be studied to determine repair vs. replacement. | System is nearing end of its life expectancy and should be considered for replacement | System should be replaced as part of the Capital Program | | | |

Building and Grounds

| | FCI | Repair Costs | Replacement Cost |
|----------|---------|--------------|------------------|
| Overall | 11.93% | \$7,034,818 | \$58,959,199 |
| Building | 12.04 % | \$7,001,887 | \$58,173,287 |
| Grounds | 04.19 % | \$32,931 | \$785,912 |

Major Building Systems

| Building System | System FCI | Repair Costs | Replacement Cost |
|---|------------|--------------|------------------|
| Roof (Shows physical condition of roof) | 90.86 % | \$1,341,501 | \$1,476,384 |
| Exterior Walls (Shows condition of the structural condition of the exterior facade) | 00.38 % | \$19,111 | \$4,964,258 |
| Windows (Shows functionality of exterior windows) | 38.20 % | \$927,028 | \$2,426,567 |
| Exterior Doors (Shows condition of exterior doors) | 25.43 % | \$41,805 | \$164,417 |
| Interior Doors (Classroom doors) | 02.31 % | \$9,177 | \$398,002 |
| Interior Walls (Paint and Finishes) | 00.48 % | \$8,567 | \$1,796,113 |
| Plumbing Fixtures | 01.33 % | \$20,448 | \$1,533,046 |
| Boilers | 09.40 % | \$199,003 | \$2,117,010 |
| Chillers/Cooling Towers | 24.06 % | \$667,839 | \$2,775,812 |
| Radiators/Unit Ventilators/HVAC | 44.81 % | \$2,184,195 | \$4,874,679 |
| Heating/Cooling Controls | 00.00 % | \$0 | \$1,530,779 |
| Electrical Service and Distribution | 00.00 % | \$0 | \$1,099,893 |
| Lighting | 00.11 % | \$4,419 | \$3,932,400 |
| Communications and Security (Cameras, Pa System and Fire Alarm) | 46.94 % | \$691,414 | \$1,472,949 |

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.