2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Hill-Freedman at Leeds School

Governance DISTRICT Report Type Middlehigh
Address 1100 E. Mt. Pleasant Ave. Enrollment 662
Philadelphia, Pa 19150 Grade Range '06-12'
Phone (Fax. 215, 400, 3534, 400, 3534, 400)
Phone (Fax. 215, 400, 3534, 400, 3534, 400)

Phone/Fax 215-400-3530 / 215-400-3531 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Hill- Turnaround Model N/A

Freedman

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	42.89%	\$36,470,031	\$85,036,297
Building	43.97 %	\$35,552,652	\$80,850,615
Grounds	21.92 %	\$917,379	\$4,185,682

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,894,252
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$7,366,379
Windows (Shows functionality of exterior windows)	34.58 %	\$1,245,223	\$3,600,743
Exterior Doors (Shows condition of exterior doors)	89.59 %	\$218,576	\$243,976
Interior Doors (Classroom doors)	201.94 %	\$1,192,647	\$590,589
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,500,521
Plumbing Fixtures	01.33 %	\$30,317	\$2,274,862
Boilers	03.23 %	\$101,394	\$3,141,396
Chillers/Cooling Towers	67.94 %	\$2,798,416	\$4,118,980
Radiators/Unit Ventilators/HVAC	139.38 %	\$10,082,284	\$7,233,454
Heating/Cooling Controls	132.68 %	\$3,013,756	\$2,271,497
Electrical Service and Distribution	185.73 %	\$3,031,322	\$1,632,112
Lighting	48.82 %	\$2,848,474	\$5,835,222
Communications and Security (Cameras, Pa System and Fire Alarm)	03.52 %	\$76,913	\$2,185,684

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.