2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Elkin LSH School

Governance DISTRICT Report Type Elementary

Address 3199 D St. Enrollment

Philadelphia, Pa 19134 Grade Range '00-04'

/Fax 215-291-4701 / 215-291-4876 Admissions Category Neighborhood

Phone/Fax215-291-4701 / 215-291-4876Admissions CategoryNeighborWebsiteWww.Philasd.Org/Schools/ElkinTurnaround ModelN/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	12.54%	\$1,514,283	\$12,073,495
Building	14.15 %	\$1,536,959	\$10,858,153
Grounds	16.21 %	\$197,045	\$1,215,708

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	63.64 %	\$490,514	\$770,719
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$571,576
Windows (Shows functionality of exterior windows)	12.30 %	\$30,701	\$249,538
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$30,574
Interior Doors (Classroom doors)	00.00 %	\$0	\$68,838
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$307,758
Plumbing Fixtures	00.00 %	\$0	\$578,167
Boilers	00.00 %	\$0	\$341,810
Chillers/Cooling Towers	84.67 %	\$379,479	\$448,180
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$787,061
Heating/Cooling Controls	158.90 %	\$392,744	\$247,158
Electrical Service and Distribution	00.00 %	\$0	\$177,588
Lighting	00.00 %	\$0	\$634,921
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$237,821

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.