2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Roosevelt School

Governance DISTRICT Report Type Elementarymiddle

Address 430 E. Washington Ln. Enrollment '00-08' Grade Range Philadelphia, Pa 19144

Neighborhood 215-951-4170 / 215-951-7762 Admissions Category

Phone/Fax Website Www.Philasd.Org/Schools/Roosevelt Turnaround Model Turnaround

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	68.78%	\$47,421,095	\$68,942,308
Building	58.56 %	\$39,483,831	\$67,422,351
Grounds	304.04 %	\$7,937,265	\$2,610,596

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$1,321,398	\$1,474,980
Exterior Walls (Shows condition of the structural condition of the exterior facade)	13.63 %	\$807,237	\$5,924,091
Windows (Shows functionality of exterior windows)	64.13 %	\$1,856,943	\$2,895,741
Exterior Doors (Shows condition of exterior doors)	139.25 %	\$273,220	\$196,207
Interior Doors (Classroom doors)	200.89 %	\$954,117	\$474,956
Interior Walls (Paint and Finishes)	42.76 %	\$916,607	\$2,143,389
Plumbing Fixtures	00.00 %	\$0	\$1,829,459
Boilers	00.00 %	\$0	\$2,526,331
Chillers/Cooling Towers	67.94 %	\$2,250,492	\$3,312,511
Radiators/Unit Ventilators/HVAC	62.51 %	\$3,636,249	\$5,817,192
Heating/Cooling Controls	122.87 %	\$2,244,567	\$1,826,753
Electrical Service and Distribution	151.54 %	\$1,989,090	\$1,312,556
Lighting	36.91 %	\$1,732,080	\$4,692,724
Communications and Security (Cameras, Pa System and Fire Alarm)	37.38 %	\$657,003	\$1,757,742

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.