2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Saul School

Governance DISTRICT Report Type High
Address 7100 Henry Ave. Enrollment 548
Philadelphia, Pa 19128 Grade Range '09-12'

Phone/Fax 215-487-4467 / 215-487-4844 Admissions Category Special Admit

Website Www.Philasd.Org/Schools/Saul Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	30.54%	\$18,119,173	\$59,326,249
Building	32.11 %	\$17,646,583	\$54,951,116
Grounds	10.80 %	\$472,590	\$4,375,133

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$1,694,101	\$1,891,000
Exterior Walls (Shows condition of the structural condition of the exterior facade)	05.28 %	\$237,222	\$4,493,578
Windows (Shows functionality of exterior windows)	43.36 %	\$1,241,149	\$2,862,575
Exterior Doors (Shows condition of exterior doors)	50.62 %	\$61,082	\$120,661
Interior Doors (Classroom doors)	73.17 %	\$286,187	\$391,108
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,647,645
Plumbing Fixtures	00.00 %	\$0	\$1,406,323
Boilers	00.00 %	\$0	\$1,942,016
Chillers/Cooling Towers	65.60 %	\$1,670,462	\$2,546,361
Radiators/Unit Ventilators/HVAC	17.80 %	\$795,781	\$4,471,734
Heating/Cooling Controls	158.90 %	\$2,231,403	\$1,404,243
Electrical Service and Distribution	39.42 %	\$397,757	\$1,008,975
Lighting	55.57 %	\$2,004,711	\$3,607,344
Communications and Security (Cameras, Pa System and Fire Alarm)	39.13 %	\$528,768	\$1,351,194

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.