2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Overbrook High School

Phone/Fax

Governance DISTRICT Report Type High Address 5898 Lancaster Ave. Enrollment 591 Philadelphia, Pa 19131 Grade Range '09-12'

215-581-5507 / 215-581-3406 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Overbrookhs Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	49.31%	\$85,820,026	\$174,048,975
Building	49.87 %	\$85,836,175	\$172,113,276
Grounds	12.21 %	\$236,297	\$1,935,699

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	05.25 %	\$203,458	\$3,874,733
Exterior Walls (Shows condition of the structural condition of the exterior facade)	15.75 %	\$2,200,406	\$13,967,251
Windows (Shows functionality of exterior windows)	82.06 %	\$7,301,516	\$8,897,656
Exterior Doors (Shows condition of exterior doors)	113.79 %	\$426,764	\$375,047
Interior Doors (Classroom doors)	98.41 %	\$1,196,323	\$1,215,668
Interior Walls (Paint and Finishes)	00.37 %	\$23,447	\$6,362,859
Plumbing Fixtures	12.25 %	\$535,416	\$4,371,232
Boilers	00.00 %	\$0	\$6,036,310
Chillers/Cooling Towers	36.77 %	\$2,910,504	\$7,914,776
Radiators/Unit Ventilators/HVAC	27.93 %	\$3,881,479	\$13,899,355
Heating/Cooling Controls	103.12 %	\$4,501,115	\$4,364,766
Electrical Service and Distribution	26.37 %	\$827,141	\$3,136,165
Lighting	16.39 %	\$1,837,687	\$11,212,599
Communications and Security (Cameras, Pa System and Fire Alarm)	07.28 %	\$305,912	\$4,199,875

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.