### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

# **Clymer School**

Governance CHARTER Report Type Elementary
Address 1201 W. Rush St. Enrollment 543
Philadelphia, Pa 19133 Grade Range '00-06'

Phone/Fax 215-227-8610 / N/A Admissions Category Neighborhood Website Www.Masterycharter.Org/Schools/Clymer Turnaround Model Renaissance Charter

Campus/

## **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	sed Deficiencies			
raciiit	y Condition index (FCI)	Replacen	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	40.66%	\$14,812,216	\$36,426,518
Building	39.48 %	\$14,046,720	\$35,581,925
Grounds	90.48 %	\$765,496	\$846,046

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$779,286	\$869,860
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,681,253
Windows (Shows functionality of exterior windows)	84.07 %	\$1,099,882	\$1,308,300
Exterior Doors (Shows condition of exterior doors)	302.62 %	\$318,756	\$105,332
Interior Doors (Classroom doors)	65.48 %	\$166,971	\$254,977
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$952,811
Plumbing Fixtures	57.28 %	\$562,549	\$982,133
Boilers	00.00 %	\$0	\$1,356,245
Chillers/Cooling Towers	65.60 %	\$1,166,613	\$1,778,301
Radiators/Unit Ventilators/HVAC	126.18 %	\$3,940,466	\$3,122,923
Heating/Cooling Controls	00.00 %	\$0	\$980,681
Electrical Service and Distribution	92.51 %	\$651,833	\$704,637
Lighting	38.10 %	\$959,824	\$2,519,259
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$943,633

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.