#### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

## Martin (Bache-Martin) School

Governance DISTRICT Report Type Elementarymiddle

Address 2201 Brown St. Enrollment

Philadelphia, Pa 19130 Grade Range '00-08'

Phone/Fax 215-684-5074 / 215-684-5446 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Bachemartin Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies						
raciiit	y Condition index (FCI)	Replacen	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
Systems						
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

### **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	40.15%	\$13,364,629	\$33,286,991
Building	37.96 %	\$13,258,196	\$34,929,276
Grounds	28.83 %	\$106,433	\$369,155

### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$2,229,520
Exterior Walls (Shows condition of the structural condition of the exterior facade)	44.58 %	\$807,237	\$1,810,760
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$790,540
Exterior Doors (Shows condition of exterior doors)	244.47 %	\$236,790	\$96,860
Interior Doors (Classroom doors)	109.37 %	\$238,513	\$218,080
Interior Walls (Paint and Finishes)	41.24 %	\$378,856	\$918,720
Plumbing Fixtures	00.00 %	\$0	\$1,831,640
Boilers	00.00 %	\$0	\$1,082,860
Chillers/Cooling Towers	50.14 %	\$711,883	\$1,419,840
Radiators/Unit Ventilators/HVAC	189.97 %	\$4,736,654	\$2,493,420
Heating/Cooling Controls	186.51 %	\$1,460,373	\$783,000
Electrical Service and Distribution	143.96 %	\$809,930	\$562,600
Lighting	51.78 %	\$1,041,608	\$2,011,440
Communications and Security (Cameras, Pa System and Fire Alarm)	39.27 %	\$295,831	\$753,420

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.