Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Catharine School

Website

Governance DISTRICT Report Type Elementary
Address 6600 Chester Ave. Enrollment 573
Philadelphia, Pa 19142 Grade Range '00-05'

Www.Philasd.Org/Schools/Catharine

Phone/Fax 215-727-2155 / 215-727-5671 Admissions Category Neighborhood

Turnaround Model

N/A

Building/System FCI Tiers

Facilit	y Condition Index (FCI)	= Cost of Assessed Deficiencies Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings	•	
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems	•	
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	38.17%	\$11,844,538	\$31,030,542
Building	39.69 %	\$11,753,769	\$29,611,273
Grounds	06.40 %	\$90,769	\$1,419,269

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$714,320
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,122,325
Windows (Shows functionality of exterior windows)	71.63 %	\$741,817	\$1,035,575
Exterior Doors (Shows condition of exterior doors)	04.19 %	\$3,494	\$83,375
Interior Doors (Classroom doors)	13.79 %	\$27,828	\$201,825
Interior Walls (Paint and Finishes)	10.20 %	\$98,521	\$966,000
Plumbing Fixtures	02.63 %	\$20,455	\$777,400
Boilers	109.34 %	\$1,173,786	\$1,073,525
Chillers/Cooling Towers	47.92 %	\$674,495	\$1,407,600
Radiators/Unit Ventilators/HVAC	105.29 %	\$2,602,715	\$2,471,925
Heating/Cooling Controls	159.14 %	\$1,235,301	\$776,250
Electrical Service and Distribution	157.08 %	\$876,127	\$557,750
Lighting	46.12 %	\$919,626	\$1,994,100
Communications and Security (Cameras, Pa System and Fire Alarm)	32.45 %	\$242,370	\$746,925

Please note that some FCIs may be over 100% because there are times when replacing a building system requires that other building systems be upgraded to complete the installation. A FCI of 0.0% represents that there are no current deficiencies with the associated system.