2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Henry School

Governance DISTRICT Report Type Elementarymiddle

Address 601 Carpenter Ln. Enrollment 482
Philadelphia, Pa 19119 Grade Range '00-08'

Phone/Fax 215-951-4006 / 215-951-4505 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Henry Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	Cost of Assess	ed Deficiencies			
raciiit	y condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
	•	Systems				
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	45.09%	\$15,321,951	\$33,980,413
Building	44.90 %	\$14,902,581	\$33,191,581
Grounds	36.77 %	\$411,235	\$1,118,448

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,351,881
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,413,914
Windows (Shows functionality of exterior windows)	88.30 %	\$1,039,999	\$1,177,854
Exterior Doors (Shows condition of exterior doors)	29.47 %	\$27,949	\$94,830
Interior Doors (Classroom doors)	04.36 %	\$10,018	\$229,554
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,035,936
Plumbing Fixtures	00.00 %	\$0	\$884,208
Boilers	46.02 %	\$561,961	\$1,221,018
Chillers/Cooling Towers	64.53 %	\$1,033,041	\$1,600,992
Radiators/Unit Ventilators/HVAC	140.06 %	\$3,937,734	\$2,811,546
Heating/Cooling Controls	158.90 %	\$1,402,967	\$882,900
Electrical Service and Distribution	189.36 %	\$1,201,245	\$634,380
Lighting	43.32 %	\$982,603	\$2,268,072
Communications and Security (Cameras, Pa System and Fire Alarm)	60.30 %	\$512,305	\$849,546

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.