### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

#### Mifflin School

Governance DISTRICT Report Type Elementarymiddle

Address 3624 Conrad St. Enrollment 299
Philadelphia, Pa 19129 Grade Range '00-08'

Phone/Fax 215-951-4007 / 215-951-4510 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Mifflin Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	38.82%	\$12,846,318	\$33,090,200
Building	37.46 %	\$11,874,874	\$31,695,993
Grounds	69.68 %	\$971,443	\$1,394,207

## **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	14.58 %	\$135,528	\$929,366
Exterior Walls (Shows condition of the structural condition of the exterior facade)	21.13 %	\$484,342	\$2,292,111
Windows (Shows functionality of exterior windows)	98.34 %	\$1,099,882	\$1,118,421
Exterior Doors (Shows condition of exterior doors)	06.63 %	\$5,973	\$90,045
Interior Doors (Classroom doors)	00.00 %	\$0	\$217,971
Interior Walls (Paint and Finishes)	33.38 %	\$203,216	\$608,741
Plumbing Fixtures	03.61 %	\$30,317	\$839,592
Boilers	00.00 %	\$0	\$1,159,407
Chillers/Cooling Towers	65.60 %	\$997,288	\$1,520,208
Radiators/Unit Ventilators/HVAC	172.07 %	\$4,593,656	\$2,669,679
Heating/Cooling Controls	158.90 %	\$1,332,175	\$838,350
Electrical Service and Distribution	00.00 %	\$0	\$602,370
Lighting	08.42 %	\$181,402	\$2,153,628
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$806,679

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.