2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Furness High School

 Governance
 DISTRICT
 Report Type
 High

 Address
 1900 S. 3Rd St.
 Enrollment
 694

 Philadelphia, Pa 19148
 Grade Range
 '09-12'

Phone/Fax 215-952-6226 / 215-952-8635 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Furness Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacem	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	41.72%	\$32,521,349	\$77,945,714
Building	41.75 %	\$32,344,644	\$77,470,217
Grounds	22.95 %	\$176,705	\$769,847

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$2,112,658
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.13 %	\$8,072	\$6,264,000
Windows (Shows functionality of exterior windows)	49.95 %	\$1,993,227	\$3,990,400
Exterior Doors (Shows condition of exterior doors)	43.32 %	\$72,859	\$168,200
Interior Doors (Classroom doors)	00.00 %	\$0	\$545,200
Interior Walls (Paint and Finishes)	12.98 %	\$298,134	\$2,296,800
Plumbing Fixtures	12.52 %	\$245,533	\$1,960,400
Boilers	56.09 %	\$1,518,308	\$2,707,150
Chillers/Cooling Towers	54.29 %	\$1,927,127	\$3,549,600
Radiators/Unit Ventilators/HVAC	97.91 %	\$6,103,520	\$6,233,550
Heating/Cooling Controls	164.70 %	\$3,224,052	\$1,957,500
Electrical Service and Distribution	67.18 %	\$944,952	\$1,406,500
Lighting	35.53 %	\$1,786,428	\$5,028,600
Communications and Security (Cameras, Pa System and Fire Alarm)	39.01 %	\$734,689	\$1,883,550

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.