2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Solis-Cohen School

Governance DISTRICT Report Type Elementary
Address 7001 Horrocks St. Enrollment 1227
Philadelphia, Pa 19149 Grade Range '00-05'

Phone/Fax 215-728-5012 / 215-728-5982 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Solis- Turnaround Model N/A

Cohen

Building/System FCI Tiers

Cost of Assessed Deficiencies							
Facility Condition Index (FCI) = Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	48.37%	\$25,623,700	\$52,970,972
Building	52.43 %	\$24,653,934	\$47,026,216
Grounds	16.31 %	\$969,766	\$5,944,756

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	99.88 %	\$3,130,369	\$3,134,286
Exterior Walls (Shows condition of the structural condition of the exterior facade)	10.66 %	\$357,990	\$3,358,810
Windows (Shows functionality of exterior windows)	117.03 %	\$1,918,026	\$1,638,910
Exterior Doors (Shows condition of exterior doors)	490.86 %	\$647,686	\$131,950
Interior Doors (Classroom doors)	204.45 %	\$653,025	\$319,410
Interior Walls (Paint and Finishes)	43.85 %	\$527,080	\$1,202,110
Plumbing Fixtures	82.78 %	\$1,018,469	\$1,230,320
Boilers	125.19 %	\$2,126,921	\$1,698,970
Chillers/Cooling Towers	54.07 %	\$1,204,455	\$2,227,680
Radiators/Unit Ventilators/HVAC	72.82 %	\$2,848,883	\$3,912,090
Heating/Cooling Controls	130.97 %	\$1,608,907	\$1,228,500
Electrical Service and Distribution	168.03 %	\$1,483,203	\$882,700
Lighting	55.91 %	\$1,764,359	\$3,155,880
Communications and Security (Cameras, Pa System and Fire Alarm)	78.84 %	\$931,904	\$1,182,090

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.