### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Meredith School**

Governance DISTRICT Report Type Elementarymiddle

Address 725 S. 5Th St. Enrollment

'00-08' Grade Range Philadelphia, Pa 19147

Neighborhood Phone/Fax 215-351-7360 / 215-351-7190 Admissions Category

Website Www.Philasd.Org/Schools/Meredith Turnaround Model N/A

# **Building/System FCI Tiers**

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	placement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	30.62%	\$8,546,973	\$27,910,282
Building	30.33 %	\$8,419,475	\$27,757,427
Grounds	33.59 %	\$127,498	\$379,592

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
<b>Roof</b> (Shows physical condition of roof)	00.00 %	\$0	\$625,195
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,046,180
Windows (Shows functionality of exterior windows)	88.45 %	\$883,075	\$998,420
Exterior Doors (Shows condition of exterior doors)	79.31 %	\$63,751	\$80,384
Interior Doors (Classroom doors)	13.16 %	\$25,602	\$194,584
Interior Walls (Paint and Finishes)	04.39 %	\$38,552	\$878,122
Plumbing Fixtures	23.49 %	\$176,043	\$749,508
Boilers	00.00 %	\$0	\$1,035,009
Chillers/Cooling Towers	49.70 %	\$674,495	\$1,357,098
Radiators/Unit Ventilators/HVAC	21.64 %	\$515,794	\$2,383,237
Heating/Cooling Controls	158.90 %	\$1,189,241	\$748,400
Electrical Service and Distribution	142.18 %	\$764,537	\$537,739
Lighting	38.76 %	\$745,152	\$1,922,555
Communications and Security (Cameras, Pa System and Fire Alarm)	38.79 %	\$279,342	\$720,127

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.