### **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

### **Barry School**

Governance DISTRICT Report Type Elementarymiddle

Address5900 Race St.Enrollment687Philadelphia, Pa 19139Grade Range'00-08'Phone/Fax215-471-2744 / 215-471-6320Admissions CategoryNeighborhoodWebsiteWww.Philasd.Org/Schools/BarryTurnaround ModelTurnaround

# **Building/System FCI Tiers**

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)	Replacem	Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

## **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	00.01%	\$5,666	\$49,951,636
Building	00.01 %	\$5,666	\$49,849,042
Grounds	00.00 %	\$0	\$104,580

#### **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$1,400,821
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$3,664,683
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,788,159
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$143,966
Interior Doors (Classroom doors)	00.00 %	\$0	\$348,497
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,669,014
Plumbing Fixtures	00.00 %	\$0	\$1,342,360
Boilers	00.00 %	\$0	\$1,853,688
Chillers/Cooling Towers	00.00 %	\$0	\$2,430,546
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$4,268,348
Heating/Cooling Controls	00.00 %	\$0	\$1,340,375
Electrical Service and Distribution	00.00 %	\$0	\$963,084
Lighting	00.16 %	\$5,666	\$3,443,273
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$1,289,738

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.