2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Spruance School

Governance DISTRICT Report Type Elementarymiddle

Address 6401 Horrocks St. Enrollment 1521
Philadelphia, Pa 19149 Grade Range '00-08'

Phone/Fax 215-537-2514 / 215-537-2933 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Spruance Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
Replacement Value							
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	42.62%	\$23,425,814	\$54,964,707
Building	45.14 %	\$23,171,369	\$51,335,274
Grounds	07.01 %	\$254,446	\$3,629,433

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	09.02 %	\$222,288	\$2,463,199
Exterior Walls (Shows condition of the structural condition of the exterior facade)	01.92 %	\$72,241	\$3,770,098
Windows (Shows functionality of exterior windows)	179.66 %	\$3,305,087	\$1,839,595
Exterior Doors (Shows condition of exterior doors)	08.87 %	\$13,140	\$148,107
Interior Doors (Classroom doors)	122.60 %	\$439,540	\$358,522
Interior Walls (Paint and Finishes)	07.86 %	\$106,093	\$1,349,309
Plumbing Fixtures	51.54 %	\$711,760	\$1,380,973
Boilers	59.79 %	\$1,140,278	\$1,907,010
Chillers/Cooling Towers	65.60 %	\$1,640,351	\$2,500,461
Radiators/Unit Ventilators/HVAC	186.10 %	\$8,172,082	\$4,391,128
Heating/Cooling Controls	158.90 %	\$2,191,180	\$1,378,931
Electrical Service and Distribution	37.60 %	\$372,503	\$990,787
Lighting	03.58 %	\$126,727	\$3,542,319
Communications and Security (Cameras, Pa System and Fire Alarm)	54.14 %	\$718,374	\$1,326,838

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.