2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Hopkinson School

Governance DISTRICT Report Type Elementarymiddle

 Address
 4001 L St.
 Enrollment
 922

 Philadelphia, Pa 19124
 Grade Range
 '00-08'

Phone/Fax 215-537-2526 / 215-537-2900 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Hopkinson Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	50.56%	\$17,006,739	\$33,634,550
Building	51.84 %	\$16,795,172	\$32,399,990
Grounds	17.14 %	\$211,567	\$1,234,560

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	39.55 %	\$307,456	\$777,343
Exterior Walls (Shows condition of the structural condition of the exterior facade)	06.61 %	\$158,640	\$2,399,150
Windows (Shows functionality of exterior windows)	166.03 %	\$1,943,654	\$1,170,650
Exterior Doors (Shows condition of exterior doors)	137.44 %	\$129,537	\$94,250
Interior Doors (Classroom doors)	239.80 %	\$547,100	\$228,150
Interior Walls (Paint and Finishes)	30.60 %	\$334,333	\$1,092,650
Plumbing Fixtures	79.11 %	\$695,213	\$878,800
Boilers	108.10 %	\$1,311,841	\$1,213,550
Chillers/Cooling Towers	52.26 %	\$831,584	\$1,591,200
Radiators/Unit Ventilators/HVAC	139.03 %	\$3,884,975	\$2,794,350
Heating/Cooling Controls	102.06 %	\$895,570	\$877,500
Electrical Service and Distribution	134.46 %	\$847,757	\$630,500
Lighting	40.68 %	\$916,957	\$2,254,200
Communications and Security (Cameras, Pa System and Fire Alarm)	84.83 %	\$716,265	\$844,350

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.