## **2015 Facility Condition Assessment Summary Report**

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

# Peirce, TM School

Governance DISTRICT Report Type Elementary
Address 2300 W. Cambria St. Enrollment 488
Philadelphia, Pa 19132 Grade Range '00-06'

Phone/Fax 215-227-4411 / 215-227-4599 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Tmpeirce Turnaround Model N/A

# **Building/System FCI Tiers**

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies				
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

# **Building and Grounds**

	FCI	Repair Costs	Replacement Cost
Overall	61.04%	\$18,843,451	\$30,870,406
Building	62.02 %	\$18,843,451	\$30,380,560
Grounds	00.00 %	\$0	\$489,846

# **Major Building Systems**

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.59 %	\$508,230	\$567,300
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,288,420
Windows (Shows functionality of exterior windows)	123.13 %	\$1,374,852	\$1,116,620
Exterior Doors (Shows condition of exterior doors)	180.11 %	\$161,922	\$89,900
Interior Doors (Classroom doors)	241.14 %	\$524,765	\$217,620
Interior Walls (Paint and Finishes)	34.49 %	\$338,694	\$982,080
Plumbing Fixtures	05.43 %	\$45,475	\$838,240
Boilers	37.09 %	\$429,293	\$1,157,540
Chillers/Cooling Towers	65.60 %	\$995,696	\$1,517,760
Radiators/Unit Ventilators/HVAC	143.01 %	\$3,811,868	\$2,665,380
Heating/Cooling Controls	158.90 %	\$1,330,032	\$837,000
Electrical Service and Distribution	157.18 %	\$945,292	\$601,400
Lighting	55.71 %	\$1,197,763	\$2,150,160
Communications and Security (Cameras, Pa System and Fire Alarm)	55.80 %	\$449,430	\$805,380

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.