2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Overbrook Ed Center School

Governance DISTRICT Report Type Elementarymiddle

Address 6722 Lansdowne Ave. Enrollment 270
Philadelphia, Pa 19151 Grade Range '00-08'

Phone/Fax 215-581-5890 / 215-581-5677 Admissions Category Citywide Website Www.Philasd.Org/Schools/Oec Turnaround Model N/A

Building/System FCI Tiers

Encilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies	
raciiit	y Condition index (FCI)	Replacem	nent Value	
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings		
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems	•	
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	01.70%	\$476,748	\$28,065,711
Building	00.89 %	\$243,766	\$27,439,245
Grounds	37.19 %	\$232,982	\$626,466

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	00.00 %	\$0	\$463,829
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,034,774
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$992,855
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$79,936
Interior Doors (Classroom doors)	00.00 %	\$0	\$193,499
Interior Walls (Paint and Finishes)	11.84 %	\$128,506	\$1,084,919
Plumbing Fixtures	00.57 %	\$4,261	\$745,331
Boilers	00.00 %	\$0	\$1,029,240
Chillers/Cooling Towers	03.94 %	\$53,134	\$1,349,533
Radiators/Unit Ventilators/HVAC	00.00 %	\$0	\$2,369,953
Heating/Cooling Controls	00.00 %	\$0	\$744,228
Electrical Service and Distribution	00.00 %	\$0	\$534,742
Lighting	00.00 %	\$0	\$1,911,839
Communications and Security (Cameras, Pa System and Fire Alarm)	00.00 %	\$0	\$716,113

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.