2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Prince Hall School

Governance DISTRICT Report Type Elementary
Address 6101 N. Gratz St. Enrollment 572
Philadelphia, Pa 19141 Grade Range '00-05'

Phone/Fax 215-276-5255 / 215-276-5803 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Princehall Turnaround Model N/A

Building/System FCI Tiers

Facility Condition Index (FCI) = Cost of Assessed Deficiencies							
raciiit	y Condition index (FCI)	Replacen	Replacement Value				
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%			
Buildings							
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.			
Systems							
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program			

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	34.05%	\$14,496,102	\$42,567,589
Building	35.17 %	\$14,345,721	\$40,790,706
Grounds	08.46 %	\$150,381	\$1,776,883

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	89.55 %	\$2,134,939	\$2,384,035
Exterior Walls (Shows condition of the structural condition of the exterior facade)	00.00 %	\$0	\$2,915,890
Windows (Shows functionality of exterior windows)	42.56 %	\$605,537	\$1,422,790
Exterior Doors (Shows condition of exterior doors)	00.00 %	\$0	\$114,550
Interior Doors (Classroom doors)	16.06 %	\$44,526	\$277,290
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$1,553,930
Plumbing Fixtures	47.02 %	\$502,246	\$1,068,080
Boilers	62.96 %	\$928,688	\$1,474,930
Chillers/Cooling Towers	00.00 %	\$0	\$1,933,920
Radiators/Unit Ventilators/HVAC	106.43 %	\$3,614,638	\$3,396,210
Heating/Cooling Controls	158.90 %	\$1,694,713	\$1,066,500
Electrical Service and Distribution	91.29 %	\$699,529	\$766,300
Lighting	33.18 %	\$909,113	\$2,739,720
Communications and Security (Cameras, Pa System and Fire Alarm)	54.15 %	\$555,704	\$1,026,210

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.