2015 Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI is a numerical representation of condition organized into five performance tiers.

Loesche School

GovernanceDISTRICTReport TypeElementaryAddress595 Tomlinson Rd.Enrollment780Philadelphia, Pa 19116Grade Range'00-05'Phone/Fax215-961-2000 / 215-961-2559Admissions CategoryNeighborhood

Website Www.Philasd.Org/Schools/Loesche Turnaround Model N/A

Building/System FCI Tiers

Eacilit	y Condition Index (FCI)	_ Cost of Assess	ed Deficiencies			
raciiit	y Condition index (FCI)		Replacement Value			
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%		
Buildings						
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.		
		Systems	•			
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program		

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	49.10%	\$24,200,354	\$49,287,082
Building	52.56 %	\$23,735,328	\$45,160,081
Grounds	11.27 %	\$465,027	\$4,127,001

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	90.78 %	\$2,513,730	\$2,769,142
Exterior Walls (Shows condition of the structural condition of the exterior facade)	03.53 %	\$114,510	\$3,248,080
Windows (Shows functionality of exterior windows)	00.00 %	\$0	\$1,584,880
Exterior Doors (Shows condition of exterior doors)	181.88 %	\$232,077	\$127,600
Interior Doors (Classroom doors)	89.00 %	\$274,917	\$308,880
Interior Walls (Paint and Finishes)	02.79 %	\$41,294	\$1,479,280
Plumbing Fixtures	61.29 %	\$729,206	\$1,189,760
Boilers	00.00 %	\$0	\$1,642,960
Chillers/Cooling Towers	65.60 %	\$1,413,213	\$2,154,240
Radiators/Unit Ventilators/HVAC	193.11 %	\$7,305,758	\$3,783,120
Heating/Cooling Controls	158.90 %	\$1,887,782	\$1,188,000
Electrical Service and Distribution	108.22 %	\$923,794	\$853,600
Lighting	85.49 %	\$2,609,098	\$3,051,840
Communications and Security (Cameras, Pa System and Fire Alarm)	79.33 %	\$906,786	\$1,143,120

Please note that some FCI's may be over 100 because there are times when replacing a building system requires that other building systems be upgraded to complete the installation.