Facility Condition Assessment Summary Report

This report provides a summary of the Facility Condition Index (FCI) value of a school facility and select major building systems. The FCI calculation represents the cost of needed repairs divided by the replacement value. The FCI is a numerical value of condition and helps to identify the need for renewal or replacement of specific parts of the facility. The FCI is particularly useful when comparing similar facilities within the same portfolio.

Morton Annex (Our Lady of Loreto) School

Governance Report Type Elementary

Address 6214 Grays Ave Enrollment

Philadelphia, Pa 19142 Grade Range '00-05'
Phone/Fax 215-727-2164 / 215-727-2341 Admissions Category Neighborhood

Website Www.Philasd.Org/Schools/Morton Turnaround Model N/A

Building/System FCI Tiers

Facilit	y Condition Index (FCI)	= Cost of Assessed Deficiencies Replacement Value		
< 15%	15 to 25%	25 to 45%	45 to 60%	> 60%
		Buildings	•	
Minimal Current Capital Funding Required	Refurbish Systems in building	Replace Systems in building.	Building should be considered for major renovation.	Building should be considered for closing/replacement.
		Systems	•	
Perform routine maintenance on system	System requires minor repairs	System should be studied to determine repair vs. replacement.	System is nearing end of its life expectancy and should be considered for replacement	System should be replaced as part of the Capital Program

Building and Grounds

	FCI	Repair Costs	Replacement Cost
Overall	43.06%	\$5,231,644	\$12,150,633
Building	42.29 %	\$5,083,781	\$12,022,338
Grounds	115.25 %	\$147,863	\$128,295

Major Building Systems

Building System	System FCI	Repair Costs	Replacement Cost
Roof (Shows physical condition of roof)	88.50 %	\$242,863	\$274,421
Exterior Walls (Shows condition of the structural condition of the exterior facade)	43.74 %	\$282,495	\$645,786
Windows (Shows functionality of exterior windows)	289.98 %	\$817,561	\$281,937
Exterior Doors (Shows condition of exterior doors)	164.06 %	\$56,673	\$34,544
Interior Doors (Classroom doors)	231.50 %	\$180,051	\$77,776
Interior Walls (Paint and Finishes)	00.00 %	\$0	\$407,081
Plumbing Fixtures	10.67 %	\$69,688	\$653,232
Boilers	31.79 %	\$122,778	\$386,189
Chillers/Cooling Towers	28.54 %	\$144,535	\$506,369
Radiators/Unit Ventilators/HVAC	83.34 %	\$741,117	\$889,248
Heating/Cooling Controls	00.00 %	\$0	\$279,248
Electrical Service and Distribution	60.17 %	\$120,734	\$200,645
Lighting	25.27 %	\$181,241	\$717,356
Communications and Security (Cameras, Pa System and Fire Alarm)	15.76 %	\$42,343	\$268,698