SIX FIELDS THAT TURN AN ENQUIRY INTO A PRICE.

What a machine shop's quote form should ask.

SHEET	01 of 09
FORMAT	Document · swipe through
DRAWN BY	34 Automation

FIELD 01 / 06

DRAWING

bracket-rev-C.step ATTACHED

LET THEM ATTACH IT.

STEP, PDF, DXF. If they can't send the drawing, you can't price it.

FIELD 02 / 06



GIVE THEM A WAY OUT.

A 'not sure' option keeps people filling it in instead of giving up.

FIELD 03 / 06



ASK IF IT REPEATS.

A one-off and a monthly batch get priced differently. Find out now.

FIELD 04 / 06

FINISH

Clear anodise

FINISH CHANGES THE PRICE.

Anodise, plate, paint or as machined. Ask before you quote, not after.

FIELD 05 / 06

TOLERANCE

±0.05 unless stated

TIGHT WHERE IT MATTERS.

Ask for any critical tolerances, so the price reflects them.

FIELD 06 / 06

REQUIRED BY

w/c 14 Dec

WHEN DO THEY NEED IT?

The date decides whether you can take the job at all.

SIX FIELDS. ONE REPLY THAT CAN BE A PRICE.

Every question you ask up front is an email you don't have to send later.



START A CONVERSATION.

We'll look at your current form and tell you what's missing.

MESSAGE 34 AUTOMATION →

REPLIES THE SAME WORKING DAY