THE MACHINIST'S WEBSITE, PAGE BY PAGE.

Seven pages. That's the whole site.

P1

HOME

What you make, to what standard, for whom. In the first line. Then one button.

P2

CAPABILITIES

One section per process: turning, milling, five-axis, finishing. Real parts in the photos.

P3

MACHINE LIST

Type, quantity, working envelope. The page that answers 'can you fit it?'



QUALITY

Accreditations, inspection kit, the tolerances you hold. Proof, not adjectives.

P5

SECTORS

The industries you serve, with the kind of work you do for each.

P6

REQUEST A QUOTE

Drawing upload, material, quantity, finish, tolerance, date. Instant acknowledgement.

P7

ABOUT

Who runs it. A real photo of the owner and the shop. Buyers want to know who they're dealing with.



SEVEN PAGES, DONE PROPERLY.

You probably don't need more than this. You need it built well.

MESSAGE 34 AUTOMATION →

REPLIES THE SAME WORKING DAY

END