From: 朱越尧

关于 Floodlight 使用 Quantum.properties 无法正常转发的解答

上次组会提到 floodlight 在使用 Quantum.properties 配置文件时无法完成正常的转发,而配置文件的主要差别在于使用了 net.floodlightcontroller.virtualnetwork.VirtualNetworkFilter 模块。这一模块的作用为:

类似于 VLAN 的 L2 基于 MAC 地址的 virtual network,每个 L2 Network 拥有多个 hosts 和一个 gateway,仅在同一个 Virtual network 中可以转发,其他包将被丢弃。

该模块提供服务接口 IVirtualNetworkService,可以完成 Virtual Network 的修改和 Hosts 的添加。同样的功能在 REST API 中也有开放。测试实验见附录一。

监听器事件分发一致性的问题

在分析 VirtualNetworkService 的功能时也涉及到了一致性问题,VirtualNetwork 对于 Packet_IN 事件(Openflow 包)的处理应该在**链路发现服务之后、转发服务之前**,从而拥有所需要的信息,也能在转发功能完成丢包操作。

在实现监听器中有两个函数需要实现,VitualNetworkFilter 的实现如下:

可见,事件分发者通过这两个函数的返回值决定了事件的分发顺序。

附录一:

虚拟机中 MiniNet 建立了如下 Topo:

S1 -- h1 -- h2

-- h3

-- h4

其中, h1-h4 的 MAC 地址分别为 00:00:00:00:00:01-04, 希望将 h1、h3 设置在同一 VLAN。

1.使用 Quantum.properties 配置运行 floodlight, MiniNet 中各 hosts 无法相互 Ping 通。

2.通过 REST API 在命令行中完成设置,目的是增加两个虚拟网,并将 h1、h3(MAC 地址和 Switch 上端口)添加到了同一个虚拟网中。

{"status":"ok"}

{"status":"ok"}

D:\SDN>curl -X put -d "{\"attachment\":{\"id\":\"NetworkId1\",\"mac\":\"00:00:00:00:00:00:00:01\"}}" http://localhost:8080/networkService/v1.1/tenants/default/network s/NetworkId1/ports/s1-eth1/attachment

{"status":"ok"}

D:\SDN>curl -X put -d "{\"attachment\":{\"id\":\"NetworkId1\",\"mac\":\"00:00:00:00:00:00:00:03\"}}" http://localhost:8080/networkService/v1.1/tenants/default/network s/NetworkId1/ports/s1-eth3/attachment

{"status":"ok"}

3.完成上述设置后,在 MiniNet 中 h1、h3 可以 Ping 通